

8.22 FMS connector position LF Series


Date of issue: September 2009

Modification date: -

Introduction

Starting from week 09.29 (Edition 2009) for the LF series the position of the FMS connector A138 has been changed. In this SEI an overview of the FMS connector position is made from situation before week 09.29 and after this week. Please note the photos show a RHD for situation1 and a LHD for situation 2.

1. Location FMS connector before week 09.29
2. Location FMS connector after week 09.29 (current situation)



Sales Engineering Information



8.22 FMS connector position LF Series

Date of issue: September 2009

Modification date: -
